Mobileye Fleet Safety Solution





Risk prediction





Human-computer

interaction

Reduce operating costs of enterprises





Tel: +66(061) 423-9444

Web: www.mpals.asia

Email: sales@mappointasia.com


Address: 128/112 Payathai Plaza

9 Floor, Payatai Road, Thung-Payatai,

Ratchathewee, Bangkok

Thailand. 10400


MS03 Reports



Events percentage



Number of events per 100km



Tracker name	Profile score	Profile level	Driving Mileage	Approaching to vehicle ahead	Approaching to vehicle ahead in city	Too fast approaching to pedestrian	Left line without blinker	Right line without blinker	Vehicle distance alarm	Exceeding speed limit
T622G-1	185	Belowaverage	291.00	49	28	1	87	85	221	113
T622G-2	112	Belowaverage	63.00	7	19	-	13	7	29	42
T622G-3	32	Average	92.00	-	-	-	12	4	14	201
T622G-4	82	Average	48.00	-	1	-	3	2	31	44
T622G-5	37	Average	120.00	-	2	-	2	1	37	107
T622G-6	212	Belowaverage	16.00	-	15	-	3	-	16	18
T622G-7	35	Average	188.00	-	-	1	9	50	5	168

6 Collision Avoidance Alerts



Forward Collision Warning



Headway Monitoring Warning



Intelligent High-Beam Control



Speed Limit Indicator & Traffic Sign Recognition



Pedestrian &
Cyclist Collision Warning



Lane Departure Warning